



Quality American Motorcycles

TB02-09-01

<http://www.atkusa.com>

Technical Bulletin

CLUTCH FRICTION PLATES - P/N 5002058

A running production change has occurred to the clutch assembly for all 2003 model year ATV and Motorcycle engines.

A new clutch friction plate P/N 5002058 with thicker friction material is now being used in all engine production.

All 2003 ATV and Motorcycle engines are assembled with the following clutch plates:

QTY	P/N	DESC
9	5001976	Clutch Plate, Steel, 1.0 mm
8	5002058	Clutch Plate, Friction, 2.82 mm

Use these plates and plate counts when installing replacement plates in older engines.

The thinner friction plate P/N 5000333 Clutch Plate, Friction 2.32 mm installed in 2001 thru early 2003 engines prior to the change have been discontinued and is no longer in production.

Our parts ordering system has been updated so that all orders for the older (thinner) clutch friction plates P/N 5000333 will automatically supercede to the new plates P/N 5002058.

When ordering the new friction plates for older units, we recommend installing 9 new metallic and new clutch springs rather than simply removing the extra metallic plate of the older assembly and utilizing the old springs.

Information is subject to change without notice.